TABLE OF CONTENTS

List c	of Illusti	rations		iii			
1.0			TION				
	1.1	Scope	of Work	3			
2.0	RESEARCH DESIGN						
	2.1	.1 Background Research					
	2.2		ic Resources Survey				
	2.3		5				
		2.3.1	Agricultural Resource Types				
		2.3.2	Residential Architectural Resource Types				
		2.3.3	Other Property Types				
				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
3.0	PREVIOUSLY SURVEYED ARCHITECTURAL RESOURCES IN						
			TUDY AREA	21			
4.0	HIST	ORICA	AL OVERVIEW	25			
	4.1		nal Historic Setting				
		4.1.1	Transformation from Colony to State (1770-1830)				
		4.1.2	Industrialization and Capitalization (1830-1880)				
		4.1.3	Suburbanization (1880-2000)				
			,				
5.0	NAT	IONAL	REGISTER EVALUATIONS OF SURVEYED HISTORIC				
			ES	42			
6.0	SUM	MARY	OF SURVEYED ARCHITECTURAL RESOURCES	58			
7.0	CON	CLUSIC	ONS AND RECOMMENDATIONS	85			
Refer	ences						
Appe	ndices						
Appendix A: Project-Surveyed Architectural Resources							
	Appendix B: Cultural Resources Survey Forms						
	Appendix C: Qualifications of Researchers						
r I .							

LIST OF ILLUSTRATIONS

Figures	EIST OF IEEOSTRATIONS	
Figure 1. Pr	roposed Roadway Improvements	2
	350 Rea and Price Map of Delaware	
	368 Beers Atlas of Delaware	
	SGS 7.5-Minute Topographic Quadrangle Series, Harrington, 1938-1981	39
_	926 and 2004 View of Commerce Street, Harrington, Looking North	
Photographs		
Photograph 1.	Lot at corner of Clark and Commerce Streets, view to southeast	60
Photograph 2.	Harrington Jeweler's on Commerce Street near Clark Street, view to southeast	60
Photograph 3.	Commerce Street with Clark Street in the background, view to northeast.	
Photograph 4.	Commerce Street, view to northwest	
Photograph 5.	The "5 Points" Intersection, Taylor Hardware Store, shed in background,	
i notograph 5.	view to north	
Photograph 6.	Heritage Park, view to north	
Photograph 7.	K-2527. View to southeast	
Photograph 8.	K-2572. View to southeast	
Photograph 9.	K-2663. View to west	
Photograph 10.	K-2664. View to northeast	
Photograph 11.	K-2665. View to northeast	69
Photograph 12.	K-2665. Detail of front door, view to east	69
Photograph 13a.	K-4615. View to southwest	
Photograph 13b.	K-4615. Modern sheds, Nos. 1, 2, and 3 (from left of photograph to right)).
	View to northwest	
Photograph 13c.	K-4615. Utility shed. View to southwest	
Photograph 13d.	K-4615. Corncrib, view to southwest	71
Photograph 13e.	K-4615. Stable. View to southwest	
Photograph 13f.	K-4615. Wagon shed. View to southwest	
Photograph 13g.	K-4615. Loafing shed, view to northeast	
Photograph 14.	K-4616. View to southeast	
Photograph 15.	K-4617. View to northeast	
Photograph 16a.	K-4622. View to west	
Photograph 16b.	K-4622. Garage attached to rear of house (former converted smokehouse)	
	View to southeast	
Photograph 16c.	K-4622. Dairy barn with milkhouse and granary; view to northwest	
Photograph 16d.	K-4622. Corncrib with wagonway in center. View to west	
Photograph 16e.	K-4622. Firewood storage shed, view to south	
Photograph 16f.	K-4622. Combine shed/corncrib. View to southeast	
Photograph 16g.	K-4622. Wagon shed with attached poultry shed, view to north	
Photograph 16h.	K-4622. Poultry sheds, view to north	
Photograph 17.	K-7381. View to northeast	
Photograph 18.	K-7382. View to east	83

U 1	 K-7383. House, barn, and shed. View to northwest K-7383. Barn. View to northwest 	
Tables	o. R 7303. Baill. View to northwest	
Table 1.	Summary Table of All Surveyed Resources in Project APE	63